

Date.....

REF. No. 10/27/18

BUILDING SAFETY CERTIFICATE

hereby certify that I have personally inspected the School building of the **San Mariono Public School** **oll Tax Naka Khandwa Road Umrikheda Dist. & Tehsil Indore (M.P.)** . The Building is being used to **in the School up to Senior Secondary Level**. The School building is constructed on Ground Floor, First floor and Second Floor. The Administrative Block of the School is at the Ground Floor.

hereby certify that construction of the building is Pucca ,RCC construction and is in accordance to the **ational Building Norms for construction of school building**. The Building of **San Mariono Public School** **oll Tax Naka Khandwa Road Umrikheda Dist. & Tehsil Indore (M.P.)** is safe for the use as an **educational building to run the school**.

Principal
San Marino Public School
Umrikhera, Khandwa Road, INDORE(M.P.)

Signature with seal of
Sub-Engineer
PWD
Munay Parishad, Rau, Indore

Director
San Marino Public School
Umrikhera, Khandwa Road, INDORE (M.P.)